
# Operating instructions and installation information

# METTLER TOLEDO

# METTLER TOLEDO MultiRange ID7-Form-XP application software



# **Contents**

		Page
1	Introduction and assembly	2
1.1	Introduction	
1.2	Safety precautions	
1.3	Installing ID7-Form-XP	
2	Formulation functions	5
2.1	STORED FORMULATION application	
2.2	FORMULATION application	
2.3	PHARMA FORMULATION application	
2.4	TOTALIZING application	
3	Settings in the master mode	22
3.1	PAC master mode block	
4	Application blocks	34
4.1	PAC application blocks	
5	What to do if?	40
6	Technical data	41
7	Appendix	42
7.1	ID7-Form-XP with Interface 4 I/O-ID7 or Relay Box 8-ID7	
7.2	FormTool-XP	
8	Index	46

Introduction and assembly ID7-Form-XP

# 1 Introduction and assembly

# 1.1 Introduction

ID7-Form-XP is an application software for the METTLER TOLEDO ID7-... weighing terminal. The functions of the ID7-Form-XP can be used after replacing the memory module.

The delivery scope of the ID7-Form-XP also includes the software FormTool-XP, with which you can also display all processes on the ID7-Form-XP on a PC, see section 7.2.

#### **Documentation**

The ID7-... weighing terminal is provided with operating instructions and installation information for the original configuration of the weighing terminal. Please see these operating instructions and installation information for basic information on working with the ID7-... weighing terminal.

These operating instructions and installation information contain additional information on installing and using the ID7-Form-XP application software.

# 1.2 Safety precautions

# 1.2.1 Installation in explosion protected ID7xx-... weighing terminal



#### **EXPLOSION HAZARD**

The ID7xx-... weighing terminal may only be opened by METTLER TOLEDO service technicians.

→ To install the ID7-Form-XP application software, please contact METTLER TOLEDO Service.

# 1.2.2 Installing in ID7-... weighing terminal



- ▲ Only authorized personnel may open the weighing terminal and install the ID7-Form-XP application software.
- ▲ Before opening the terminal, pull the power plug or switch off the power supply for terminals with a fixed connection.

# 1.3 Installing ID7-Form-XP

# 1.3.1 Opening ID7-... weighing terminal

#### **Desk unit**

- 1. Unscrew the screws on the underside of the cover.
- 2. Lay down the cover toward the front. In doing so, make sure that the cables are not damaged.

ID7-Form-XP Introduction and assembly


#### Wall unit


- 1. Unscrew the screws on the underside of the cover and fold the cover toward the front. When doing so, make sure that the cables are not damaged.
- 2. Fold open the mounting plate.


#### Panel unit

- 1. Unscrew the 10 hex bolts on cut-out on the inside of the switch cabinet.
- 2. Remove the cover from the switch cabinet and fold toward the front. When doing so, make sure that the cables are not damaged.
- 3. Fold open the mounting plate.

# 1.3.2 Mounting ID7-Form-XP







# 1.3.3 Closing ID7-... weighing terminal

# Closing desk unit

- 1. Lay device on cover and fix slightly in place with 3 screws.
- 2. Press unit into cover so that 3 engaging springs engage.
- 3. Tighten screws.



#### **CAUTION**

The IP68 protection type can only be guaranteed when the weighing terminal is closed again properly.

- → The 3 engaging springs must be completely engaged.
- → Make sure that the keypad cable is not pinched.

Introduction and assembly ID7-Form-XP

# Closing wall unit

- 1. Fold in the mounting plate.
- 2. Position the cover and screw on again. When doing so, make sure that no cables are pinched.

# Closing panel unit


- 1. Fold in the mounting plate and position the cover on the cut-out again.
- 2. Secure the cover on the switch cabinet from the inside with 10 screws. When doing so, make sure that no cables are pinched.

# 2 Formulation functions

The ID7-Form-XP offers 4 different formulation applications, which you can select in the master mode:

STORED FORMULATION, FORMULATION, PHARMA FORMULATION and TOTALIZING. With the FormTool-XP software provided you can operate or monitor all applications from a PC, see section 7.2.

# 2.1 STORED FORMULATION application



In this application you can call up the stored formulas and use them as the basis for the new formulation. A maximum of 150 formulas can be stored.

Depending on the settings in the master mode,

- you can fill the components into one container consecutively (section 2.1.1) or fill
  each component of a formulation into a separate container (section 2.1.2) or
  work through the formulation in the batch mode (section 2.1.3),
- the target weight of the stored formula is adopted or you are asked to enter a target weight,
- an automatic rescaling is offered for a component that was filled outside the tolerance (section 2.1.4),
- you can monitor the adherence of the tolerances with the DELTATRAC when weighing in to a target weight,
- the ID7-Form-XP provides you with support for warehouse management.

# **Prerequisite**

The STORED FORMULATION application is set in the master mode.

#### **Function keys**

With the STORED FORMULATION application the function keys have the following assignment at the start:

START STORED FORMULATION
Starts the application

→ Press any function key to start the application.

# If the function keys have a different assignment

→ Press the FUNCTION CHANGE key repeatedly until the function key assignment shown above appears.

# Assignment of the function keys when working through stored formulas

The assignment of the function keys adjusts to the operating sequence.

# Selecting formula

<b>← F</b>	F →	SELECT	СОМРО	SUM	STOP
View formulas: Descending	View formulas: Ascending	Select formula	View components of the formula	Call up accumulated sum of the formula	Cancel application

# **Selecting component**

<b>← C</b>	$\mathbf{C}  o$	SELECT	INVENT	-	STOP
View components: Descending	View components: Ascending	Select component	Information on stock level and consumption of raw material	-	Park formula, cancel application

# Weighing in component

_	_	PLUS	MANUAL	-	STOP
_	_	Add component to formula	Enter weight values manually	-	Return to "Select component"

# Information after completing formula

FORMU	<b>← C</b>	<b>C</b> →	_	_	STOP
Call up the actual value for the formula and the deviation from the target weight	View dispensed components: Descending	View dispensed components: Ascending	-	-	Return to "Select formula"

# Information after completing batch mode

_	← <b>B</b>	$B \rightarrow$	_	_	STOP
-	View dispensed batches: Descending	View dispensed batches: Ascending	-	_	Return to "Select formula"

# Messages

Depending on the setting in the master mode, messages appear in the display during formulation.

→ Carry out request and confirm the message with the ENTER key if necessary to continue formulation.

#### 2.1.1 Filling all components into a common container

#### **Prerequisite**

VERTICAL FILLING is set in the master mode.

#### Selecting formula

- 1. Start the application with the START STORED FORMULATION key.
- 2. If PASSWORD ON is selected in the master mode, enter your user name and password and confirm with ENTER.
- 3. Place container on weighing platform.

The container is automatically tared when WORKING SEQUENCE ON is selected in the master mode.

4. Select formula with <-F and F-> keys and confirm with SELECT.

— or –

Enter the number of the stored formula (1 ... 150) with the number block and confirm with SELECT or <-F or F->.

– or –

Press Code A key, enter formula name and confirm with ENTER.

– or –

Press Code A key, enter formula identification and confirm with ENTER.

5. When TARGET WEIGHING ON is set in the master mode, enter the target weight of the formula and confirm with the ENTER key.

The target value and the name of the formula are printed.

# Selecting and dispensing component

1. Select component with <-C and C-> keys and confirm with SELECT.

– or –

Enter number of component with the number block and confirm with SELECT or <-C or C->.

– or –

Press Code B key, enter component name and confirm with ENTER.

– or –

Press Code B key, enter component identification and confirm with ENTER.

- 2. Fill component.
- 3. Press PLUS key.

Target value, tolerance and actual value of the component are printed.

4. To fill the remaining components into the container, repeat steps 1 to 3.

#### **Notes**

• If the weight of a component lies within the tolerance, the value for the deviation is shown in brackets < ... >.

- Components with the unit Pcs. do not contribute to the weight sum of the formula.
- If ORDER OF COMPONENTS FIXED is selected in the master mode, components cannot be selected, but instead must be worked through in the specified order.
- If SELECT BARCODE ON is selected in the master mode, each component must be confirmed with a barcode.
- Prints can be configured in the INTERFACE master mode block.

# Finishing formula

# Information on formula just dispensed

1. When the message CLEAR SCALE appears, remove weighing sample from the weighing platform.

The name, actual weight and deviation from the target weight for the formula are printed.

The actual weight and the difference to the target weight for the formula just dispensed appear in the display.

2. Display the actual weight and difference to the target weight for the components with the <-C and C-> keys.

#### Closing formula

3. Close formulation with the STOP key. The formula selection appears again.

# 2.1.2 Filling each component into separate container

#### **Prerequisite**

BATCH FILLING is selected in the master mode.

#### Selecting formula

- 1. Start the application with the START STORED FORMULATION key.
- 2. If PASSWORD ON is selected in the master mode, enter your user name and password and confirm with ENTER.
- 3. Select formula with <-F and F-> keys and confirm with SELECT.

– or –

Enter the number of the stored formula (1 ... 150) with the number block and confirm with SELECT or <-F or F->.

- or -

Press Code A key, enter formula name and confirm with ENTER.

– or –

Press Code A key, enter formula identification and confirm with ENTER.

4. When TARGET WEIGHING ON is set in the master mode, enter the target weight of the formula and confirm with the ENTER key.

The target value and the name of the formula are printed.

#### Selecting and dispensing component

1. Select component with <-C and C-> keys and confirm with SELECT.

- or -

Enter number of component with the number block and confirm with SELECT or <-C or C->.

- or -

Press Code B key, enter component name and confirm with ENTER.

– or –

Press Code B key, enter component identification and confirm with ENTER.

2. Place container on weighing platform.

The container is automatically tared when WORKING SEQUENCE ON is selected in the master mode.

- 3. Fill component.
- 4. Press PLUS key.

Target value, tolerance and actual value of the component are printed.

- 5. Remove container from weighing platform.
- 6. To fill the remaining components, repeat steps 1 to 5.

#### **Notes**

- If the weight of a component lies within the tolerance, the value for the deviation is shown in brackets < ... >.
- If ORDER OF COMPONENTS FIXED is selected in the master mode, components cannot be selected, but instead must be worked through in the order entered.
- Components with the unit Pcs. do not contribute to the weight sum of the formula.
- If SELECT BARCODE ON is selected in the master mode, each component must be confirmed with a barcode.
- Prints can be configured in the INTERFACE master mode block.

# Finishing formula

# Information on formula just dispensed

1. When the message CLEAR SCALE appears, remove weighing sample from the weighing platform. The name, actual weight and deviation from the target weight for the formula are printed.

The actual weight and the difference to the target weight for the formula just dispensed appear in the display.

2. Display the actual weight and difference to the target weight for the components with the <-C and C-> keys.

#### Closing formula

3. Close formulation with the STOP key. The formula selection appears again.

#### 2.1.3 Batch mode

#### **Prerequisite**

BATCH MODE is selected in the master mode.

#### Selecting formula

- 1. Start the application with the START STORED FORMULATION key.
- 2. If PASSWORD ON is selected in the master mode, enter your user name and password and confirm with ENTER.
- 3. Select formula with <-F and F-> keys and confirm with SELECT.
  - or -

Enter the number of the stored formula (1  $\dots$  150) with the number block and confirm with SELECT or <-F or F->.

- or -

Press Code A key, enter formula name and confirm with ENTER.

– or –

Press Code A key, enter formula identification and confirm with ENTER.

- 4. Enter number of batches and confirm with ENTER key.
- 5. When TARGET WEIGHING ON is set in the master mode, enter the target weight of the formula and confirm with the ENTER key.

The target value and the name of the formula are printed.

#### Selecting and dispensing component

- 1. Select component with <-C and C-> keys and confirm with SELECT.
  - or —

Enter number of component with the number block and confirm with SELECT or <-C or C->.

- or -

Press Code B key, enter component name and confirm with ENTER.

- or -

Press Code B key, enter component identification and confirm with ENTER.

Then the following display appears for information: ITERATION 1/n.

- 2. Enter batch ID and confirm with ENTER.
- 3. Place container on weighing platform.

The container is automatically tared when WORKING SEQUENCE ON is selected in the master mode.

- 4. Fill component.
- 5. Press PLUS key.

Target value, tolerance and actual value of the component are printed.

6. Remove container from weighing platform.

7. To fill the remaining batches, repeat steps 2 to 7. The ITERATION display is counted up until the last batch n/n. When the component for all batches is filled, the message ITERATION COMPLETE appears.

8. To fill the remaining components, repeat steps 1 to 8. The batch ID need not be entered again.

#### **Notes**

- If the weight of a component lies within the tolerance, the value for the deviation is shown in brackets < ... >.
- Components with the unit Pcs. do not contribute to the weight sum of the formula.
- If ORDER OF COMPONENTS FIXED is selected in the master mode, components cannot be selected, but instead must be worked through in the order entered.
- If SELECT BARCODE ON is selected in the master mode, each component must be confirmed with a barcode.
- Prints can be configured in the INTERFACE master mode block.

#### **Completing batch**

# Information on batch just dispensed

- 1. When all batches have been filled, the name, actual weight and difference to the target weight are printed.
  - The batch ID, actual weight and tare for a batch of the formula just dispensed appear in the display.
- 2. Display the actual weight and tare for the remaining batches with the <-B and B-> key.

#### Closing batch

3. Close formulation with the STOP key. The formula selection appears again.

# 2.1.4 Correcting target value

When a component has been filled above tolerance, all remaining components of the formula can be adjusted accordingly with the rescaling.

#### **Prerequisite**

RESCALING ON is selected in the master mode and the dispensed component has exceeded the upper tolerance by a maximum of 50 %.

→ When the message RESCALING? appears, press the ENTER key. Target values of the remaining components are automatically adjusted.

#### **Notes**

 If the actual values of components already worked through lie outside the new tolerance, you will be requested to redispense or reenter these components manually.

- A rescaling is only possible once during a formulation process.
- If after rescaling the newly rounded target value for a component with the unit Pcs. lies outside the tolerance, this will result in cancelling.
- With a component that has to be redispensed, a lower and upper limit will be displayed and printed in place of the tolerance.

# 2.1.5 Accepting known weight value for the formula

- Press MANUAL key.
- Enter weight value and confirm with ENTER.
   The weight value is stored in the formula memory and the component counter is increased by 1.

#### Note

With the FUNCTION CHANGE key the weight unit for entering known weight values can be selected.

# 2.1.6 Displaying, saving or deleting accumulated sum for current formula

#### Manual

If CLEAR SUM MANUALLY is set in the master mode, the sum can be displayed or deleted at any time in the formulation mode.

- 1. Press the SUM key in the "Select formula" input mask.
  The sum appears above the selected formula in the display.
- 2. To save the sum and return to the formula, press the SAVE function key.

– or –

To clear the accumulated sum and return to the formula, press the CLEAR function key.

#### **Automatic**

If CLEAR SUM AUTOMATICALLY is set in the master mode, the sum can only be displayed in the formulation mode.

→ Press the SUM key in the "Select formula" input mask.

The sum appears for 5 seconds above the selected formula in the display.

#### 2.1.7 Working with lot and batch numbers

#### Lot number

When ENTRY LOT NUMBER ON is selected in the master mode, a request that the lot number for the formula be entered appears when the formula is started.

#### **Batch number**

When ENTRY BATCH NUMBER ON is selected in the master mode, a request that the batch number be entered appears each time a component is called.

#### Note

The designations LOT NUMBER and BATCH NUMBER can be changed in the master mode.

# 2.1.8 Filling components in several steps

If in the VERTICAL FILLING operating mode, INPUT BATCH NUMBER ON, MULTIPLE is selected in the master mode, a component can be dispensed in up to 6 steps. A maximum of 200 steps are possible per formula.

- 1. Select component and enter batch number.
- Partially fill component and press PLUS key.
   The component still appears in the component selection, however now with a reduced target weight.
- 3. Select next component and enter batch number.
- 4. Partially or completely fill component and press PLUS key.
- 5. Call the component already partially dispensed again and apply the displayed batch number or enter a new batch number.
- 6. Fill another part of the component or finish dispensing the component and press the PLUS key.
- 7. Continue until all components are dispensed up to the target weight.

#### 2.1.9 Parking formulas

If a formula cannot be completely dispensed, because, for example, a raw material must first be refilled, this formula can be "parked" and completely dispensed at a later time.

## Parking formula

- Press the CANCEL key in the component selection.
   The question PARK FORMULA? appears.
- Answer the question with YES.
   The formula selection appears in the display. A new formula can be dispensed.

# Finishing dispensing parked formula

- Call the parked formula again with the formula ID.
   In the component selection now only the components not yet dispensed appear.
- 2. Fill missing components and end formula.

#### Note

Only one formula can be parked. If an additional formula is to be parked, then the first parked formula is deleted.

#### 2.1.10 Inventory management with ID7-Form-XP

If the inventory level has been entered when stocking the raw materials, then the inventory level can be displayed when dispensing this raw material.

→ Press the INVENTORY key during component selection. The inventory level and the consumption since the last inventory receipt are displayed consecutively.

# 2.1.11 Formulation of STORED FORMULATION on multiple weighing platforms

Up to 3 weighing platforms can be connected to the ID7-Form-XP, see chapter "Basic functions" of the operating and installation instructions for the weighing terminal ID7-...


# Note for formulation of stored formulation on multiple weighing platforms

→ Use a separate container on each weighing platform.

#### 2.1.12 Printout example

Date	02/02/02		
Time	15:16:17	Component	Sugar
Formula No.	1	•	ME3612/23.01.02
Formula ID	52	Raw material No.	623
Lot number	#1234	1st formulated weight	0.500 kg
Formula name	Cream toffee	2nd formulated weight	
Component counter	5		· ·
Target	1.620 kg		
Tolerance	0.160 kg	Component	Cream
Previous message	ì	Batch number	ME3784/18.01.02
Previous message	3	Raw material No.	15
Previous message	5	1st formulated weight	0.100 kg
Next message	6	2nd formulated weight	0.100 kg
Next message	8		· ·
Target value correction	0		
		Component	Milk
		Batch number	ME3234/31.01.02
		Raw material No.	69
	Baking powder	1st formulated weight	
Batch number	ME5461/01.02.02	2nd formulated weight	0.500 kg
Raw material No.	713		
1st formulated weight			
2nd formulated weight	0.020 kg	Batch ID	B40
		Batch net	1.640 kg
		Gross	1.900 kg
Component	Flour	Tare	0.260 kg
Batch number	ME1667/20.01.02	Batch ID	B41
Raw material No.	52	Batch net	1.600 kg
1st formulated weight	0.500 kg	Gross	1.860 kg
2nd formulated weight	0.480 kg	Tare	0.260 kg
		===========	

# 2.2 FORMULATION application



In this application, you can measure out several components into a container one after the other. Each formula and each component can be provided with an identification.

## **Prerequisite**

In the master mode, the FORMULATION application is selected.

#### **Function keys**

With the FORMULATION application the function keys are allocated as follows:

MAN	SUM	CONT	PLUS	_	_
Enter weight values manually	Display net sum and print out	Subtotal for current container	Add weight values	_	_

→ Press the relevant function key, in order to select the function.

#### **Example**

→ Press the MAN key.

Then you can enter the known weight values manually via the keyboard.

#### When the function keys have a different allocation

→ Press the FUNCTION CHANGE key until the function keys allocation displayed above appears.

#### 2.2.1 Formulation

- 1. Press CODE A key and enter the identification for the formula.
- 2. Place the empty container on the weighing platform and tare.
- 3. Press CODE C key and enter the identification for the first component.
- Add first component.
   The display indicates the net weight of the current component.
- 5. Press PLUS key.
  - The weighing platform tares automatically and the display registers 0.000 kg. The current net sum in the container is determined and the component counter is increased by 1.
- 6. In order to add further components in the container, repeat steps 3 to 5. Max. 15 components per container are possible.

# Changing the container

7. If more than 15 components are filled into a container or the container is overfilled: Press CONT key and place a new container on the weighing platform. The container counter is increased by 1, the component counter is set back to zero for the new container and the tare weight is deleted.

#### Closing formulation

- 8. When fewer than 15 components have been dispensed into container, press CONT key.
- 9. Clear weighing platform.
- 10. Press SUM key.

The net sum is displayed and automatically printed out.

- 11. If the net sum is to be placed into temporary storage, press the ENTER key.
- 12. Press CLEAR key.

The net sum is deleted and the component counter and the container counter are reset.

# 2.2.2 Carrying over the known weight value to the sum

- Press MAN key.
- Enter the weight value and confirm with ENTER.
   The weight value is stored in the sum memory and the component counter is increased by 1.

#### Note

With the FUNCTION CHANGE key you can select the weight unit for entering known weight values.

#### 2.2.3 Tolerance control with DeltaTrac

Using DeltaTrac in the application FILLING you can monitor on weighing in the compliance of the tolerances with the target weight, see chapter "Additional functions" in the operating instructions and installation information ID7-... weighing terminal.

The weight value is only added to the sum when the weight value lies within the tolerance limits.

- 1. Preset the DeltaTrac target values for the current component.
- 2. Add the component.

If there is an addition beyond the tolerance limits, remove the container and fill again or delete the target value.

3. Press PLUS key.

The components are only carried over to the sum when they lie within the tolerance limits.

#### Note

With the FUNCTION CHANGE key you can select the weight unit for entering the DeltaTrac target values.

# 2.2.4 FORMULATION on multiple weighing platforms

Up to 3 weighing platforms can be connected to the ID7-Form-XP, see chapter "Basic functions" in the operating instructions and installation information ID7-... weighing terminal.

#### Note for formulation on multiple weighing platforms

→ Use a separate container on each weighing platform.

#### 2.2.5 Recalling information regarding the FORMULATION application


Using the key sequence INFO, FUNCTION key you can recall information regarding the FORMULATION application.

INFO, MAN Display last entered weight value.

INFO, CONT Display number and subtotal for the current container.

INFO, PLUS Display the last weighed components.

# 2.3 PHARMA FORMULATION application



In this application, you can fill each component of a formula in a separate container. Each formula and each component can be individually provided with an identification.

#### **Prerequisite**

In master mode, the PHARMA FORMULATION application is selected.

#### **Function keys**

With the PHARMA FORMULATION application the function keys are allocated as follows:

MANUAL	SUM	CONTAINER
Enter weight value manually	Display net sum and print out	Close container

→ Press the relevant function key, in order to choose the functions.

#### Example

→ Press the MANUAL key.

Then you can enter the known weight values manually via the keyboard.

# If the function keys have a different allocation

→ Press the FUNCTION CHANGE key until the function keys allocation displayed above appears.

#### 2.3.1 Pharma formulation

- 1. Press CODE A key and enter the identification for the formula.
- 2. Place the conatiner on the weighing platform and tare. The container counter is increased by 1.
- 3. Press CODE C key and enter the identification of the first component.
- 4. Add the components.
  - The display shows the net weight of the current component.
- Press CONTAINER key.
  - The tare weight of the container is deleted.
- 6. In order to add further components, repeat steps 2 to 5.

# Closing pharma formulation

7. Press SUM key.

The net sum is displayed and automatically printed out.

- 8. If the net sum is to be placed into temporary storage, press the ENTER key.
- 9. Press CLEAR key.

The net sum is deleted, and the component and container counters are reset.

# 2.3.2 Carrying over the weight values to the sum

- 1. Press MANUAL key.
- Enter the weight value and confirm with ENTER.
   The weight value is stored in the sum memory and the item counter is increased by 1.

#### Note

With the FUNCTION CHANGE key you can select the weight unit for entering known weight values.

#### 2.3.3 Tolerance control with DeltaTrac

With DeltaTrac in the application FILLING you can monitor on weighing in the compliance of the tolerances with a target value, see chapter "Additional functions" in the operating instructions and installation information ID7-... weighing terminal. The weight value is only added to the sum when the weight value lies within the tolerance limits. Possible settings in the master mode:

- FILL A target value applicable to all fillings.
- COMPOUNDING A target value for each container or each component.

#### **Filling**

- Preset DeltaTrac target values.
- 2. Add component.

If there is an addition beyond the tolerance limits, remove the container and fill again or delete the target value.

3. Press CONTAINER key.

The components are only then carried over to the sum if they lie within the tolerance limits.

4. For the additional components, repeat steps 2 and 3.

The DeltaTrac target values remain stored until new values are entered or the values are deleted.

#### Compounding

1. Preset the DeltaTrac target values for the components.

# 2. Add component.

If there is an addition beyond the tolerance limits, remove the container and fill again or delete the target value.

3. Press CONTAINER key.

The component is only then carried over to the sum if it lies within the tolerance limits.

For additional components, repeat steps 1 to 3.
 The DeltaTrac target values are deleted after each component.

#### Note

With the FUNCTION CHANGE key you can select the weight unit for entering the DeltaTrac target values.

# 2.3.4 PHARMA FORMULATION on multiple weighing platforms

Up to 3 weighing platforms can be connected to the ID7-Form-XP, see chapter "Basic functions" in the operating instructions and installation information ID7-... weighing terminal.

# Note for formulation on multiple weighing platforms

→ Use a separate container on each weighing platform.


# 2.3.5 Recalling information regarding the PHARMA FORMULATION application

Using the key sequence INFO, FUNCTION key you can recall information regarding the PHARMA FORMULATION application.

INFO, MANUAL Display the last entered weight value.

INFO, CONTAINER Display the sum for the current container.

# 2.4 TOTALIZING application



In this application, you can determine the total weight of several items. Each sum and each item can be provided with an identification.

## **Prerequisite**

In the master mode the TOTALIZING application is selected.

#### **Function keys**

With the TOTALIZING application the function keys are allocated as follows:

MANUAL	SUM	PLUS
Enter weight values manually	Display gross sum and print out	Add weight values

→ Press the relevant function key in order to select the function.

#### Example

→ Press the MANUAL key.

Then you can enter the weight values manually via the keyboard.

#### If the function keys have a different allocation

→ Press the FUNCTION CHANGE key until the function keys allocation displayed above appears.

#### 2.4.1 Totalizing

- 1. Press CODE A key and enter the identification for the sum.
- 2. Press CODE C key and enter the identification for the first item.
- 3. Put the first item on.
- 4. Press PLUS key.

The item counter is increased by 1 and displayed with the gross sum.

5. Place the additional items on and repeat steps 2 to 4.

# **Closing totalizing**

6. Press SUM key.

The gross sum is displayed and printed out automatically.

- 7. In order to place the gross sum into temporary storage, press the ENTER key.
- 8. In order to delete the gross sum, press the CLEAR key. The item counter is reset.

# 2.4.2 Transferring the weight value to the sum

- 1. Press MANUAL key.
- Enter the weight value and confirm with ENTER.
   The weight value is stored in the sum memory and the item counter is increased by 1.

#### Note

With the FUNCTION CHANGE key you can select the weight unit for entering known weight values.

# 2.4.3 TOTALIZING on multiple weighing platforms

Up to 3 weighing platforms can be connected to the ID7-Form-XP, see chapter "Basic functions" in the operating insructions and installation information ID7-... weighing terminal.

Changing the weighing platform is always possible when using the TOTALIZING application.

# 2.4.4 Recalling information regarding the TOTALIZING application

Using the key sequence INFO, FUNCTION key you can recall information regarding the TOTALIZING application.

INFO, MANUAL Display the last entered weight value.

INFO, PLUS Display the number of items weighed until now.


Settings in the master mode ID7-Form-XP

# 3 Settings in the master mode

# 3.1 PAC master mode block

#### 3.1.1 Overview of the PAC master mode block

In this block, the following settings are possible:



# Legend

- Blocks on a **grey** background are described extensively in the following.
- Factory settings are printed in **bold** type.
- Blocks that appear only under specific conditions are dotted.

#### Note

With the FormTool-XP software provided you can operate or monitor all applications from a PC, see section 7.2.

# 3.1.2 Settings in the PAC master mode block

APPLICATION	Selecting application					
STORED FORMULATION	Store formulas and use as basis for the new formulation. A maximum of 150 formulas with a maximum of 100 components each can be stored. A maximum of 2,000 components are possible for all formulas together.					
RAW MATERIALS	Create/edit raw materials database. A maximum of 500 raw materials can be stored.					
	EDIT RAW MATERIALS, see section 3.1.3.					
	PRINT RAW MATERIALS					
	DELETE ALL RAW MATERIALS					
MESSAGES	Up to 5 messages can be assigned to each formula - two to each component. A total of 200 messages with a maximum of 24 characters can be stored. Create/edit message database, see section 3.1.4.					
	EDIT MESSAGES, see section 3.1.4.					
	PRINT MESSAGES					
	<ul> <li>MESSAGES ON/OFF – When MESSAGES OFF is selected, no messages are displayed during formulation, even if the formula or the component is provided with messages.</li> </ul>					
	DELETE ALL MESSAGES					
FORMULAS	Create/edit formula database.					
	EDIT FORMULAS, see section 3.1.5.					
	PRINT FORMULAS					
	CLEAR ALL FORMULAS					
OPERATING MODE	Dispensing of the components in a common or a separate container:					
	VERTICAL FILLING – Fill all components into a common container; factory setting					
	<ul> <li>SEVERAL CONTAINER – Fill each component into a separate container</li> <li>BATCH MODE – The same formula can be dispensed simultaneously up to 100</li> </ul>					
	times, i.e. each component is filled a corresponding number of times.					
WORKING SEQUENCE	When WORKING SEQUENCE ON is selected (factory setting), the prompt LOAD CONTAINER appears at the start of formulation and the container is automatically tared.					
TARGET WEIGHING	Adjust formula target weight:					
	ON — The formula target weight can be adjusted before each new formulation process					
	OFF – The stored formula target weight is accepted as the formula target weight; factory setting					

Settings in the master mode ID7-Form-XP

APPLICATION	Selecting application				
RESCALING	Correct component target value following incorrect dispensing:				
	<ul> <li>ON – If the actual value exceeds the upper tolerance by less than 50 %, the operator can carry out a rescaling. Target values and tolerances of the other components are then corrected by the same percentage. If the actual value of components already filled lies outside their new tolerance limits, the operator will be asked to redispense these components. Factory setting.</li> <li>OFF – The actual value is only accepted when it lies within the tolerance.</li> </ul>				
DELTATRAC	ON — During weighing in the adherence to the tolerances is monitored.				
	OFF – Only the weight value is shown in the display; factory setting.				
LOT NUMBER	Each formula can be marked with a lot number.				
	ENTER LOT NUMBER — When ENTER LOT NUMBER ON is selected, the entry of the lot number is requested at the start of the formula.				
	DESIGNATION LOT NUMBER — Change the text "LOT NUMBER".				
BATCH NUMBER	Each component can be marked with a batch number.				
	ENTER BATCH NO. — When ENTER BATCH NO. ON is selected, the entry of the batch number is requested for each component.  Additional settings:				
	<ul> <li>ON Entry of the batch number is requested for each component.</li> </ul>				
	SINGLE The component must be filled at one time.				
	MULTIPLE The component can be filled in several steps.				
	<ul> <li>ON+ The last batch number entered is displayed each time the component is called up. The batch number can be accepted or a new batch number can be entered.</li> </ul>				
	SINGLE The component must be filled at one time.				
	MULTIPLE The component can be filled in several steps.				
	<ul> <li>OFF The batch number is not requested.</li> </ul>				
	DESIGNATION BATCH NO. — Change the text "BATCH NUMBER".				
CLEAR SUM	<ul> <li>AUTOMATIC – Sums are automatically cleared daily at the entered time.</li> <li>MANUAL – Sums must be cleared manually; factory setting.</li> </ul>				
SELECT BARCODE	If SELECT BARCODE ON is selected, each component must be confirmed with a barcode during formulation.				
PRINTING BEFORE FORMULATION	When PRINTING BEFORE FORMULATION ON is selected, the selected formula is printed out before starting on the GA46 printer.				
MANUAL ENTRY	When MANUAL ENTRY OFF is selected, the manual entry function is deactivated during dispensing.				

APPLICATION	Selecting application				
ORDER OF	<ul> <li>FIXED – The components must be dispensed in the specified order.</li> </ul>				
COMPONENTS	VARIABLE – The components can be dispensed in any desired order; factory setting.				
PRINTING AFTER FORMULATION	When PRINTING AFTER FORMULATION ON is selected, the dispensed formula is printed out on the GA46 printer after completion.  Not possible in the batch mode.				
PASSWORD	When PASSWORD ON is selected, the application STORED FORMULATION can only be run after entering a password.				
USER LIST	Entry of USER NAMES and related PASSWORDS.				
FORMULATION	Fill the formula components one after the other into the container.				
PHARMA FORMULATION	Fill the formula components one after the other into separate containers.  Possible settings:				
	FILL – Fill all components to the same target value.				
	COMPOUNDING — Fill each component to a different target value.				
TOTALIZING	Totalize several items.				

ITEM COUNTER	Setting the item counter with the application TOTALIZING				
START VALUE	Possible values: 1 9999 (factory setting: 1)				
STOP VALUE	Possible values: 1 9999 (factory setting: 9999)				

UNIT MANUAL ENTRY	Selecting preferred unit for weight values, which are entered with the MANUAL key
UNIT	Possible units: g, kg, lb, ozt, dwt, oz, Stk, Pcs Factory setting: kg

DETAILED DISPLAY	Switching on/off additional info line in display
	If DETAILED DISPLAY ON is set, an additional line for info appears in the display, e. g. "Item: 2/9999"
	For FORMULATION, PHARMA FORMULATION and TOTALIZING only. Factory setting: DETAILED DISPLAY OFF.

Settings in the master mode ID7-Form-XP

SUBTRACTIVE WEIGHING	Totalising with subtractive weighing
	If SUBTRACTIVE WEIGHING ON is selected, totalising can also occur with subtractive weighing.  For the TOTALISING application only.  Factory setting: SUBTRACTIVE WEIGHING OFF.

RESET PAC	Resetting all functions to the factory settings				
	APPLICATION	Stored formulation			
	OPERATING MODE	Vertical filling			
	WORKING SEQUENCE	On			
	TARGET WEIGHING	Off			
	RESCALING	On			
	DELTATRAC	Off			
	LOT NUMBER	Off			
	BATCH NUMBER	Off			
	CLEAR SUM	Manual			
	SELECT BARCODE	Off			
	PRINTING BEFORE FORMULATION	Off			
	MANUAL ENTRY	Off			
	ORDER OF COMPONENTS	Variable			
	PRINTING AFTER FORMULATION	Off			
	PASSWORD	Off			
	ITEM COUNTER	Start value = 1, Stop value = 9999			
	UNIT MANUAL ENTRY	kg			
	DETAILED DISPLAY	Off			
	SUBTRACTIVE WEIGHING	Off			

#### 3.1.3 Editing raw materials

#### Input mask

The following input masks appear for editing the raw materials database (Example):

ID 001 : H20 NAME : WATER

INVENTORY : 25.0 kg

WARNING : NO INVENTORY MANAGEMENT

MES. NO. : 123

CONSUMED : 2.0 kg

STOCKED : 02.02.02 07.15.01

QUANTITY USE : 3

**Legend** ID nnn Identification of raw material,

alphanumeric, max. 20 characters

NAME Name of raw material,

alphanumeric, max. 30 characters

INVENTORY Quantity of raw material stocked.

The inventory quantity is updated with each dispensing

WARNING Warning message for inventory management,

The following settings are possible:

NO INVENTORY MANAGEMENT No warning

NEGATIVE INVENTORY Warning when inventory is 0 or below INVENTORY LESS THAN COMP. Warning when the quantity for the currently

required component is not long in stock

INVENTORY BELOW 10 % Warning when inventory is below 10 % of

the original value

MES NO. Message to be displayed when this raw material is

dispensed.

CONSUMED \* Display of the raw material consumed up to this point.

This value is updated with each dispensing.

STOCKED \* Display of when the inventory was last added to.

QUANTITY USE \* Display of the number of formulas the raw material is used

in.

\* These values are only displayed, and cannot be edited.

Settings in the master mode ID7-Form-XP

# **Function keys** The function keys are assigned as follows:

<->	<b>v</b>	>	F►	EDIT	<b>↑</b>
Select parameters	Scroll back in raw materials and warnings	Scroll forward in raw materials and warnings	Select function of function key F5	EDIT DEL SEARCH GO STORE	End raw material, with prompt regarding changes

#### Example 1 Creating new raw material with the ID 005

- 1. Select ID 005 in the raw material input mask with the keys < , >.
- 2. Press the F5 EDIT key and enter the raw material ID, e.g. RS 005. Confirm the entry with the ENTER key.
- 3. Select the next parameter NAME with the <-> key.
- 4. Press the F5 EDIT key and enter the raw material name, e.g. Water. Confirm the entry with the ENTER key.
- 5. Select the next parameter INVENTORY with the <-> key.
- 6. Press the F5 EDIT key and enter the stocked quantity, e.g. 25.0 (kg). Confirm the entry with the ENTER key.
- 7. Select the next parameter WARNING with the <-> key.
- 8. Select the type of warning for inventory management with the keys < , >.
- 9. Select the next parameter MES. NO. on the second page of the input mask with the <-> key.
- 10. Press the F5 EDIT key and enter the message number, e.g. 123. Confirm the entry with the ENTER key.
- 11. End Raw Material with the ↑ key. The question CHANGES? appears.
- 12. If the new raw material is to be stored in the database, then press the YES key and otherwise the NO key.

#### Example 2 Updating inventory of raw material SUGAR

- 1. Select the parameter NAME in the raw material input mask with the <-> key.
- 2. Select the function SEARCH for the F5 key with the key F▶.
- 3. Press the key F5 SEARCH and enter the raw material name SUGAR. Confirm the entry with the ENTER key; the raw material SUGAR is displayed.
- 4. Select the parameter INVENTORY with the <-> key.
- 5. Press the key F5 EDIT and enter the new inventory quantity (remaining quantity + received).
  - Confirm the entry with the ENTER key.
  - The CONSUMED parameter is reset to 0, and the STOCKED parameter shows the date and time of the input just made.
- 6. End raw material with the 1 key. The question CHANGES? appears.
- 7. If the new raw material is to be stored in the database, then press the YES key and otherwise the NO key.

# 3.1.4 Editing messages

The ID7-Form-XP can store 200 messages of the message database, which can then be assigned to the formulas, components and raw materials.

The message database is divided into 3 areas:

- Action messages, e.g. LOAD CONTAINER or ZERO-SET SCALE.
   As soon as the action is carried out, the ID7-Form-XP switches to the next step.
- 2. Fixed messages, e.g. WEAR GOGGLES!

  Here the ID7-Form-XP expects a confirmation with the ENTER or CLEAR key.
- 3. Free messages. Only freely definable messages can be edited.

No.	Action messages	No.	Fixed messages
001	LOAD CONTAINER	021	HANDLE WITH CARE !
002	LOAD CONTAINER, <tare></tare>	022	EXPLOSIVE !
003	CHANGE CONTAINER	023	WEAR GOGGLES!
004	RELIEVE SCALE	024	FLAMMABLE !
005	CHANGE SCALE, <enter></enter>	025	FRAGILE!
006	SPECIFY TARE	026	WEAR GLOVES!
007	ZERO-SET SCALE	027	CAUSTIC!
800	ENTER LOT NUMBER	028	WEAR BREATHING PROTECTION !
009	ENTER BATCH NUMBER	029	TOXIC!
010	CONFIRM RAW MATERIAL	030	IRRITATING!
011	<enter></enter>		Free messages
012	ENTER FORMULA	031	
013	ENTER COMPONENT	032	
014	ENTER CUSTOMER	033	
015	ENTER ORDER NUMBER	034	
016	SELECT SCALE 1	035	
017	SELECT SCALE 2	036	
018	SELECT SCALE 3		
019	CHANGE CONTAINER, <tare></tare>		
020		200	

Settings in the master mode ID7-Form-XP

#### Message input mask

The following input mask appears for editing the messages (example):

MESSAGE : 035/200 FREE MESSAGE

**CONTAINER RED** 

1st line Number of message (035) and type of message 4th line Contents of the message (maximum of 24 characters)

#### **Function keys**

The function keys are assigned as follows:

<	^	_	F▶	EDIT	$\uparrow$
Scroll back in messages	Scroll forward in messages	_	Select function of function key F5: EDIT, DEL etc.	EDIT DEL GO SEARCH	End message; settings are accepted as displayed

# Example Creating message 036 "CONTAINER GREEN"

- 1. Select the function GO for the F5 key with the key F▶.
- 2. Press the key F5 GO and enter the message number 36.

Confirm the entry with the ENTER key.

The message number and the message type (free message) are displayed in the 1st line.

If the message already exists, the current function appears in the 4th line.

- 3. Select the function EDIT for the F5 key with the key F▶.
- 4. Press the key F5 EDIT and enter the message text. Confirm the entry with the ENTER key.
- End message with the ↑ key.

#### 3.1.5 Editing formulas

# Input mask formula header

The following input mask appears for editing the general formula data (example):

F 001 : AX0815B (10.5 kg)

NAME : COLA

MES : 100 123 150 - 099 101

COMP : 001/003 (005)

# **Function keys**

The function keys are assigned as follows:

<->	<	>	F►	EDIT	$\uparrow$
Select parameters	Scroll back in formulas	Scroll forward in formulas	Select function of function key F5	EDIT DEL GO SEARCH	End formula, changes are applied.

Legend

F nnn Identification of formula,

alphanumeric, max. 20 characters

NAME Name of formula,

alphanumeric, max. 30 characters

MES Message numbers for 3 messages at the start of the formula and

2 messages after working through the formula.

000 means that no message is output.

COMP Running component in the formula/number of components in the

formula

(raw material ID of running component)

# Input mask for component

The following input mask appears for editing the individual formula components (example):

F 001 : FORMULA 001

C 001 : RS 001

: WATER

MESSAGES : 002 - 003 (1/2)

F 001 : FORMULA 001

C 001 : RS 001

WEIGHT : 9 kg

TOLERANCE : 0.5 kg (2/2)

Settings in the master mode ID7-Form-XP

# **Function keys** The function keys are assigned as follows:

<->	<	>	F▶	ADD	<b>↑</b>
Select parameters	Scroll back in compo- nents	Scroll forward in components	Select function of function key F5	ADD EDIT DEL GO SEARCH STORE	End component, with prompt regarding changes

**Legend** F nnn Identification of formula

C nnn Raw material ID,

Raw material name

MESSAGES Number of messages that are displayed before the start of the

component and after dispensing of the component.

WEIGHT Target weight of the component. With the change function key

you can change the unit during the entry. The tolerance unit

adjusts automatically.

TOLERANCE Tolerance of the component

# Example 1 Creating new formula with F 005

#### Formula header

- 1. Select F 005 in the formula input mask with the keys < , >.
- 2. Press the F5 EDIT key and enter the formula ID, e.g. FORMULA 005. Confirm the entry with the ENTER key.
- 3. Select the next parameter NAME with the <-> key.
- 4. Press the F5 EDIT key and enter the formula name, e.g. FANTA. Confirm the entry with the ENTER key.
- 5. Select the next parameter MES with the <-> key.
- 6. Press the key F5 EDIT and enter the number of the first message to be displayed at the start of the formula, e.g. 001.

If no message is to be displayed, enter the number 000.

Confirm the entry with the ENTER key.

7. Select the next message with the <-> key and proceed as for the first message. A total of 3 messages can be selected for the start of the formula and 2 messages for after the end of the formula.

# **Adding components**

- 1. Select the parameter COMP. in the Formula input mask with the <-> key.
- Press the key F5 ADD.The display changes to the input mask for the component.
- 3. Select the desired raw material in the raw materials database with the keys < , >.
- 4. Select the parameter MESSAGES with the <-> key.

- 5. Press the key F5 EDIT and enter the number of the message to be displayed at the start of the component, e.g. 001.
  - If no message is to be displayed, enter the number 000.
  - Confirm the entry with the ENTER key.
- 6. Select the 2nd message to be displayed after dispensing the component with the <-> key.
- 7. Press the key F5 EDIT and enter the message number. Confirm the entry with the ENTER key.
- 8. Switch to the 2nd page of the input mask for the components with the <-> key; the WEIGHT parameter is selected.
- 9. Press the key F5 EDIT and enter the target weight of the component. Confirm the entry with the ENTER key.
- 10. Select the next parameter TOLERANCE with the <-> key.
- 11. Press the key F5 EDIT and enter the tolerance of the component. Confirm the entry with the ENTER key.
- 12. End Component with the ↑ key.
  The question CHANGES? appears.
- 13. If the new component is to be stored in the formula database, then press the YES key and otherwise the NO key.
- 14. Create further components in the same way.

#### Example 2 Changing existing component C 003

- 1. Select the parameter COMP. in the formula input mask with the <-> key.
- 2. Select the function GO for the F5 key with the key F▶.
- 3. Press the key F5 GO and enter the component number 3. Confirm the entry with the ENTER key; the component C 003 is displayed.
- 4. Select the parameter to be changed with the <-> key, e.g. WEIGHT.
- 5. Press the key F5 EDIT and enter the new target weight of the component. Confirm the entry with the ENTER key.
- 6. If additional parameters are to be changed, proceed in the same manner.
- End component with the ↑ key.
   The question CHANGES? appears.
- 8. If the change component is to be stored in the formula database, then press the YES key and otherwise the NO key.

Application blocks ID7-Form-XP

# 4 Application blocks

In the following description, the application blocks are shown in the syntax for the MMR command set. When used with the SICS command set, please observe the SICS conventions, see Operating instructions and installation information for ID7-... weighing terminal.

# 4.1 PAC application blocks

# 4.1.1 General application blocks

No.	Content	Format	
301	Pac version	Response:	$[A_{ }B_{ }]_{ }I_{ }D_{ }/_{ }F_{ }O_{ }r_{ }m_{ }P_{ }a_{ }C_{ }]_{ }V_{ }X_{ }{ }X_{ }X$
302	Program number	Response:	[A <sub>1</sub> B <sub> </sub> _ I <sub>1</sub> P <sub>1</sub> 7 <sub>1</sub> 2 <sub>1</sub> - <sub>1</sub> 0 <sub>1</sub> - <sub>1</sub> 0 <sub>1</sub> x <sub>1</sub> x <sub>1</sub> x <sub>1</sub> x <sub>2</sub> ]
316	Unit manual entry	Response: Write:	A_B _ Unit A_W 3_1_6 _ Unit
318 321	Identification data Code A Code D	Response: Write: Comment:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
341	Conversion factor for the neutral unit with manual entry	Response: Write:	[A_B _ Weight value _ Unit] [A_W 3_4_1 _ Weight value _ Unit]

ID7-Form-XP Application blocks

# 4.1.2 Application blocks FORMULATION, PHARMA FORMULATION, TOTALIZING

No.	Content	Format	
310	Counter	Response: Comment:	Application FORMULATION, PHARMA FORMULATION: Component counter Application TOTALIZING: Item counter
311	Container counter	Response: Comment:	A_BNumber_4 only with the application FORMULATION, PHARMA FORMULATION
312	Component counter current container	Response: Comment:	$A_B_N$ Number_4 only with the application FORMULATION
313	Sum net weight	Response:	A B Weight value Unit
314	Sum gross weight	Response: Comment:	[A_B]_ Weight value]_ Unit] only with the application TOTALIZING
315	Manual entry	Response:	A B Weight value Unit
317	Start value item counter	Response: Write: Comment:	A_BNumber_4  A_W 3_1_7 _ Number_4  only with the application TOTALIZING
322	Sum net weight current container	Response: Comment:	[A_B _ Weight_value _ Unit] only with the application FORMULATION
323	Net weight last start weight	Response:	A_BWeight valueUnit
324 338	Net weight component 115	Response: Comment:	$A_B_I =  $ Identification (Text_20) $ _{I} =  $ Weight value $ _{I} =  $ Unit only with the application FORMULATION
339	Tare weight current container	Response: Comment:	A_BWeight valueUnit] only with the application FORMULATION, PHARMA FORMULATION
340	Stop value item counter	Response: Write: Comment:	A_BNumber_4  A_W 3_4_0Number_4  only with the application TOTALIZING
342	Gross weight last totalizing procedure	Response:	A_BWeight valueUnit]
343	Tare weight last totalizing procedure	Response: Write:	[A_B Weight value  Unit] [A_W 3_4_3 _ Weight value _ Unit]

Application blocks ID7-Form-XP

# 4.1.3 Application blocks STORED FORMULATION

No.	Content	Format	Format		
344_001  344_500	Messages, write protection	Response: Write:	[A_B _   Contents (Text_24)       Write protection (Number_1)    [A_W 3_4_4x_x_x     Contents (Text_24)   \$_\$    Write protection (Number_1)    O: Unlock, no write protection (factory setting)		
		Note:			
			1: Lock, with write protection  xxx = 001 500		
345	Current formula	Response:	A B Formula No. (No_3)       Formula ID (Text_30)         Lot No. (Text_20)       Formula name (Text_30)         Number of components (Number_3)		
			Target weight (weight value)		
			Tolerance (weight value) Unit		
			Msg. before 1 (No_3)   _   Msg. before 2 (No_3)   _   _		
			Msg. after 1 (No_3)     Msg. after 2 (No_3)		
		Write:	Msg. after 3 (No_3) Flag (Number_1)  A_W 3_4_5 _ Formula No. (Number_3)   \$   \$		
		WITHG.	Lot No. (Text_20) \$   \$		
			Target weight (weight value) Unit \$ \$ \$		
			Number of batches (Number_3)		
		Comment:	The target weight can be changed by the operator when		
			TARGET WEIGHING ON is selected in the master mode.		
			The target weight can only be described while the formula is		
			available for selection.		
			Formula No.: 001 150		
			No. of components: 001 100		
			Message No.: 000 200 000: no message		
			Flag: 0: Target values as stored 1: Rescaled		

ID7-Form-XP Application blocks

No.	Content	Format	
346	Actual values, current component	Response:	A B Comp. No. (No_3) Batch No. (No_3)   Raw mat. ID (T_30) Raw mat. name (T_30)   Target weight (weight value) Unit   Tolerance 1 (weight value) Unit   Tolerance 2 (weight value) Unit   Msg. before (No3) Msg. after (No3)   Flag (Number_1) Manual entry (Number_1)
		Write:	A   W   3   4   6   Component No. (Number_3)   \$   \$   Batch No. (Text_20)
		Comment:	Tolerance_2 is not determined until after rescaling.  The target weight can only be described while the component is available for selection.  Component No.: 001 100  Message No.: 000 200 000: no message  Flag: 0: Target value as stored 1: Rescaled  Manual entry: 0: Component weighed 1: Manual entry
347	Inventory, current component	Response:	A B _ Inventory (weight value) _ Unit    Inventory receipt (Date_Time)    Consumed (weight value) _ Unit
348_001  348_100	Current target values, Components 1100, current formula	Response:	Raw mat. ID (T_30) Raw mat. name (T_30) Target weight (weight value) Unit Tolerance 1 (weight value) Unit Tolerance 2 (weight value) Unit Msg. before (No_3) Msg. after (No_3) Blag (Number_1) Batch No.: 001 100
		Comment:	Batch No.: 001 100 Tolerance 1: Tolerance of stored formula Tolerance 2: Tolerance of stored formula Message No.: 001 200
349	Tare current container	Response:	A B Tare (weight value) Unit
350	Batch	Response:	A B Number of batches (Number_3)  Current batch (Number_3)  Component name (Text_30)
351	Last batch weight	Response:	A_B Batch (weight value) Unit
352_001  352_100	Batch details	Response:	A_B _ Batch ID (Text_20)  Net (weight value) _ Unit  Gross weight (weight value) _ Unit  Tare (weight value) _ Unit

Application blocks ID7-Form-XP

No.	Content	Format	
353	Total weight of current formula	Response:	A_B _ Formula net weight (weight value) _ Unit   Formula gross weight (weight value) _ Unit   Deviation (weight value) _ Unit
355_001  355_100	Partial weights of component	Response: Comment:	Partial weight 1 (Weight value) Unit  Batch 2 (Text_20)  Partial weight 2 (weight value) Unit   Batch 6 (Text_20)  Partial weight 6 (weight value) Unit  Only possible in the operating modes VERTICAL FILLING or BATCH FILLING with the setting BATCH NO. ONE, MULTIPLE
361_001  361_200	Messages	Response: Write: Comment:	$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$
362_001  362_500	Raw materials	Response: Write:	A_B _ Raw material ID (Text_20) Raw material name (Text_30) Inventory (weight value) Unit Message (No_3) Warning (No_1) Inventory receipt (Date_Time)
		Comment:	Inventory (weight value) Unit \\$,\$  Message (No_3) \\$,\$ Warning (No_1)  nnn = 001 500  Warning 0: no inventory management  Warning 1: Warning if negative inventory  Warning 2: Warning if the inventory for the selected component is not reached  Warning 3: Warning if < 10 % of original inventory
363_001  363_150	Formula mode	Response: Write: Comment:	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$

ID7-Form-XP Application blocks

No.	Content	Format	
364	Formula header	Response:	Formula ID (Text_10)
		Comment:	Message before 1 (No_3) \$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\\$\
365_001  365_100	Components of current formula	Response:	A_B _ Raw mat. ID (T_20) Raw mat.I name (T_30) Target weight (weight value) Unit Tolerance (weight value) Unit Message before (No_3) Message after (No_3)
		Write:	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
		Comment:	nnn = 001 100  Messages: 000 200  000 = no message  Writing only possible if a formula is loaded via AB 363 in the Edit mode and not until the header is written via AB 364
366	Formula status	Response: Comment:	
398	Report No.	Response:	A_B _  Serial number (Number_6)

What to do if ...? ID7-Form-XP

#### What to do if ...? 5

Error / Display	Possible causes	Remedy
OVERFLOW SUM GROSS OVERFLOW SUM NET	Capacity of buffer for gross sum or for net sum exceeded	→ Delete sum and form sub-sum
OVERFLOW CONTAINER	Capacity of buffer for container counter exceeded	<ul><li>→ Reset counter by deleting sum</li><li>→ Suitably divide sum or recipe</li></ul>
OVERFLOW ITEMCOUNTER	Item counter or component counter has reached stop value	<ul><li>→ Reset counter by deleting sum</li><li>→ Select suitable start and stop value</li></ul>
OVERFLOW MAN. INPUT	Manual entry would exceed capacity of sum buffer	<ul> <li>→ Check value of manual entry</li> <li>→ Check value of FACTOR FOR NEUTRAL UNIT</li> </ul>
WEIGHT TOO LOW	Totalizing or formulation with weight which is too low	→ Place item on platform or fill component; watch 10 d weight threshold.
NEGATIVE COMPONENT	Current component negative	→ Place component removed last on scale again until second display is positive
NO VALUE	Manual entry: No value or zero entered	→ Enter permissible value
CONT. NOT FINISHED	Sum key pressed without having formed container sum for all scales used beforehand	→ Form all container sums
CLEAR SUM	Sum not cleared	→ Clear sum

ID7-Form-XP Technical data

# 6 Technical data

Formulation functions					
FORMULATION, PHARMA	FORMULATION, PHARMA FORMULATION, TOTALIZING applications				
Sum memory	Up to 8 places including decimal point				
Manual entry memory	Up to 6 places including decimal point				
Item counter	Up to 9,999 with freely selectable start and stop value, only for TOTALIZING application				
Component counter	Up to 9,999, only for FORMULATION and PHARMA FORMULATION applications				
Container counter	Up to 9,999, only for FORMULATION and PHARMA FORMULATION applications				
STORED FORMULATION	STORED FORMULATION application				
Formula database	max. 150 formulas with a maximum of 100 components, max. 2000 components over all formulas				
Raw material database	max. 500 raw materials				
Message database	max. 200 messages, which can be assigned to raw materials, components and formulas. Thereof 20 action messages and 10 fixed messages, which cannot be changed				
Batch operation	max. 100 batches				
Partially filling	A component can be dispensed in up to 6 steps. A maximum of 200 steps are possible per formula				
Target weighing	The stored formula target value can be adjusted before the start of formulation				
Rescaling	If a component has been dispensed over tolerance, the remaining components can be recalculated for the higher formula weight				

Appendix ID7-Form-XP

# 7 Appendix

## 7.1 ID7-Form-XP with Interface 4 I/O-ID7 or Relay Box 8-ID7

The following input assignments apply when using the ID7-Form-XP together with an Interface 4 I/O-ID7 or a Relay Box 8-ID7:

### Input signals

Input	Key	Function in the application STORED FORMULATION		
Input 1	Key F3	SELECT PLUS	for selection of formula or component for formulation	
Input 2	Key F6	STOP		
Input 3	Tare weighing platform			
Input 4	ENTER key			

#### 7.2 FormTool-XP

## 7.2.1 System requirements

- PC with one of the operating systems Windows 98, Windows 2000 or Windows XP
- ID7-Form-XP with a PC connected via a serial interface or Ethernet

### 7.2.2 Installing and initialising FormTool-XP

#### Installing

- 1. Insert CD and run "formtool.exe".
- 2. Follow the instructions that appear on the screen in the further course of the installation.
- 3. Reboot the PC after completing the installation.

#### Initialising

- 1. Switch on ID7-Form-XP.
- 2. Start FormTool-XP ("Start -> Programs -> Mettler-Toledo -> FormTool-XP").
- 3. Select the interface in the "Interface Settings" window and configure the interface parameters in accordance with the settings on the ID7-Form-XP.

Then the FormTool-XP is ready for operation, the display of the ID7-Form-XP is shown on the PC.


ID7-Form-XP Appendix

### 7.2.3 Operation with FormTool-XP

FormTool-XP is operated analogously to operation on the weighing terminal ID7-Form-XP. In addition, FormTool-XP also offers extensive reporting functions for evaluating the formulas.

Additional information on FormTool-XP is contained in the online help. Several examples of the operating interface are shown on the following pages.


**Formulation** During formulation weighing and formula data are shown in real time.




Appendix ID7-Form-XP

**Editing raw materials** 

Raw materials can be easily be created or edited.




**Editing formulas** Formulas can be easily be created or edited.



ID7-Form-XP Appendix

**Reporting** Extensive reporting functions are available for evaluating the formulas.



Index ID7-Form-XP

#### Index 8

A Action messages 29	Printing before formulation 24		
Adding components 32 Application 15, 17, 20, 23	<b>R</b> Raw materials database 41		
<b>B</b> Batch mode 10, 23, 41 Batch number 13, 24	Rescaling 11, 24, 41 Reset Pac 26		
C Clear sum 24 Clear total 12 Compounding 19	Safety precautions 2 Select barcode 9, 24 Separate container 8 Stored formulation 5, 23, 41 Subtractive weighing 26		
DeltaTrac 18, 24 Documentation 2	<b>T</b> Target weighing 7, 8, 10, 23, 41		
E Editing formulas 31 Editing messages 29 Editing raw materials 23, 27 Error messages 40	Technical data 41  U Unit manual entry 25		
F	V Vertical filling 7, 23		
Filling 18, 25 Fixed messages 29 Formula database 41 Formulation functions 5, 41 Free messages 29 Function keys 5, 15, 17, 20	W What to do if? 40		
Installation 2 Inventory level 28 Inventory management 14 Item counter 25 Iteration 10			
L Lot number 13, 24			
Manual entry 24 Message database 41 Messages 6, 23, 29			
<b>O</b> Operating mode 23 Order of components 9, 25			
P Parking formulas 13 Printing after formulation 25			

46



22005901A

Subject to technical changes © Mettler-Toledo (Albstadt) GmbH 04/10 Printed in Germany 22005901A

## Mettler-Toledo (Albstadt) GmbH

D-72458 Albstadt

Tel. ++49-7431-14 0, Fax ++49-7431-14 232

Internet: http://www.mt.com