


OnSite PM[™]

Minimize out-of-tolerance failures!



Failure rate by component

Over 95% of pipette failures are due to sealing system wear. This is predictable and preventable.

Pipette Inspection includes



IMPORTANT: All units must be completely decontaminated of any radioactive or biohazardous materials prior to inspection.

- ☐ Stops problems before failure occurs
- Provides higher assurance of pipette reliability
- ☐ For RAININ® and Pipetman® pipettes

OnSite Preventive Maintenance (OSPM) provides:

- Detailed pipette inspection
- Pressure leak-test
- Pipette cleaning incl. piston maintenance
- Minor repairs

- New seal every visit
- New shaft first visit, then every 3 years
- Replace missing, broken, or worn parts
- Service reports, dated stickers

To schedule an OSPM Clinic for your lab, or for more information...

Contact RAININ at 800-543-4030

Easy and convenient:

Pipette maintenance done right in your lab!

RAININ, Pipet-Lite, Pipetting 360° and Pipetting 360° logo are registered trademarks and OnSite PM is a service mark of Rainin Instrument, LLC. Pipetman is a registered trademark of Gilson S.A.S. © 2010 Rainin Instrument, LLC.

